

Redline / Strikeout Version

Part III, Attachment III-E

Geology Report

Part III
Attachment III-E

GEOLOGY REPORT

Pescadito Environmental Resource Center
MSW No. 2374
Webb County, Texas

PESCADITO
ENVIRONMENTAL RESOURCE CENTER

Initial Submittal March 2015

Revised September 2015

Revised November 2015

Revised January 2016

Technically Complete March 11, 2017

Modified August 2017

Prepared for:

Rancho Viejo Waste Management, LLC
1116 Calle del Norte
Laredo, TX 78041

Prepared by:

APTIM Environmental &
Infrastructure, Inc.
(f/k/a CB&I Environmental &and
Infrastructure, Inc.)



APTIM

12005 Ford Rd, Suite 600
Dallas, TX 75234

This document is released for the purpose of permitting only under the authority of Michael W. Oden, P.E #67165. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650.

Table of Contents

1.0 Introduction..... 1
2.0 Hydrogeologic Setting 4

Figure III-E.0-1 – Original and Revised Permit Boundaries 12
Figure 2 – Generalized Conceptual Model of Site Hydrogeology 10

Appendix III-E.1 Regional Geology and Hydrogeology
Appendix III-E.2 Subsurface Investigation Report
Appendix III-E.3 Geotechnical Data Report
Appendix III-E.4 Summary of Hydrogeologic Testing in Selected Piezometers
Appendix III-E.5 Supplemental Subsurface Investigation Report – Phase V

This document is released for the purpose of permitting only under the authority of Michael W. Oden, P.E #67165. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650.