

Part III
Attachment III-D
Appendix III-D.5

GEOTECHNICAL ANALYSES REPORT

Pescadito Environmental Resource Center
MSW No. 2374
Webb County, Texas

PESCADITO

ENVIRONMENTAL RESOURCE CENTER

Initial Submittal MARCH 2015

Revised SEPTEMBER 2015

Revised August 2016


Prepared for:

Rancho Viejo Waste Management, LLC
1116 Calle del Norte
Laredo, TX 78041

Prepared by:



CB&I Environmental & Infrastructure, Inc.
12005 Ford Rd, Suite 600
Dallas, TX 75234



This document is released for the purpose of permitting only under the authority of Jesse P. Varsho, P.E. #114074. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650

This document is released for the purpose of permitting only under the authority of Michael W. Oden, P.E. #67165. **It has been updated to include new Appendix III-D.5-7 only.** No other revisions have been made. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650.

**Part III
Attachment III-D
Appendix III-D.5
GEOTECHNICAL ANALYSES REPORT**

TABLE OF CONTENTS

Introduction..... 1

Organization of Report..... 1

Slope Stability Analyses 2

Short-Term and Long-Term Shear Strength Under Static Conditions..... 2

Critical Cross Section 2

Modeled Stability Scenarios 3

Slope Stability Results 3

Foundation Bearing Capacity Analyses..... 4

Landfill Foundation Settlement, Waste Settlement, and Soil Liner Strain Analyses 5

Foundation Settlement and Soil Liner Strain 5

Waste Settlement 5

Final Cover Stability Analysis 6

Sideslope Liner Runout Analyses (with and without an Anchor Trench) 6

APPENDICES

Appendix III-D.5-1 Summary of Geotechnical Design Parameters

Appendix III-D.5-2 Slope Stability Analyses

Appendix III-D.5-3 Foundation Bearing Capacity Analyses


Appendix III-D.5-4 Landfill Foundation Settlement, Waste Settlement, and Soil Liner Strain Analyses

Appendix III-D.5-5 Final Cover Stability Analysis

Appendix III-D.5-6 Sideslope Liner Runout Analyses (with and without an Anchor Trench)

Appendix III-D.5-7 Slope Stability Analysis with Flexible Membrane Cover

This document is released for the purpose of permitting only under the authority of Michael W. Oden, P.E. #67165. **It has been updated to include new Appendix III-D.5-7 only.** No other revisions have been made. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650.




This document is released for the purpose of permitting only under the authority of Jesse P. Varsho, P.E. #114074. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650


GEOTECHNICAL ANALYSES REPORT APPENDICES

- APPENDIX III-D.5-1 SUMMARY OF GEOTECHNICAL DESIGN PARAMETERS
- APPENDIX III-D.5-2 SLOPE STABILITY ANALYSES
- APPENDIX III-D.5-3 FOUNDATION BEARING CAPACITY ANALYSES
- APPENDIX III-D.5-4 LANDFILL FOUNDATION SETTLEMENT, WASTE SETTLEMENT, AND LINER STRAIN ANALYSES
- APPENDIX III-D.5-5 FINAL COVER STABILITY ANALYSIS
- APPENDIX III-D.5-6 SIDESLOPE LINER RUNOUT ANALYSES

APPENDIX III-D.5-7 FINAL COVER STABILITY ANALYSIS
WITH FLEXIBLE MEMBRANE LINER



This document is released for the purpose of permitting only under the authority of Michael W. Oden, P.E. #67165. **It has been updated to include new Appendix III-D.5-7 only.** No other revisions have been made. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650.



This document is released for the purpose of permitting only under the authority of Jesse P. Varsho, P.E. #114074. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650

