

**Part III
Attachment III-C**

FACILITY SURFACE WATER DRAINAGE REPORT

**Pescadito Environmental Resource Center
MSW-2374
Webb County, Texas**




March 2015

**Prepared for:
Rancho Viejo Waste Management, LLC
1116 Calle del Norte
Laredo, TX 78041**

**Prepared by:
CB&I Environmental and
Infrastructure, Inc.**



**12005 Ford Rd, Suite 600
Dallas, TX 75234**



This document is released for the purpose of permitting only under the authority of Michael W. Oden, P.E. #67165. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650.

Table of Contents

1.0 Introduction..... 1


Appendix III-C.1 Facility Surface Water Drainage Report Narrative

Appendix III-C.2 Drawings

Appendix III-C.3 Drainage Analysis

Appendix III-C.4 HydroCAD Model Outputs

Appendix III-C.5 Erosion Control Plan



1.0 Introduction

This Facility Surface Water Drainage Report (FSWDR) for the Pescadito Environmental Resource Center (PERC) has been prepared to meet or exceed the regulations applicable to stormwater management outlined in Title 30 of the Texas Administrative Code (30 TAC), Section 330, Municipal Solid Waste; specifically, Sections 330.63(c), 330.301, 330.303, 330.305, and 330.307.

The various appendices to the Attachment III-C include documentation that the facility design complies with the requirements of 330.303 of this title (relating to Surface Water Drainage for Municipal Solid Waste Facilities). Additionally, a surface water drainage report has been prepared to satisfy the requirements of Subchapter G of this chapter (relating to Surface Water Drainage).